
Evidence Book 17



Township of Guelph/Eramosa Cultural Heritage Review Document Book Index

TAB DOCUMENT

- 1 Unterman McPhail Associates Comments July 14, 2014
- 2 Unterman McPhail Associates Comments October 1, 2014
- **3** GRA Response to Unterman January 26, 2015
- **4** Unterman McPhail Associates Sign Off Letter August 26, 2015



UNTERMAN MCPHAIL ASSOCIATES

HERITAGE RESOURCE MANAGEMENT CONSULTANTS

540 RUNNYMEDE ROAD TORONTO ONTARIO M6S 2Z7

T 416 766 7333 F 416 763 4082

E umcarubm@pathcom.com

Memorandum

to: Liz Howson, Principal

Macaulay Shiomi Howson Ltd., Toronto, ON

from: Richard Unterman, Principal

date: July 14, 2014

re: Review of the Report "Cultural Heritage Assessment Review for the

proposed Hidden Quarry, Part Lot 1 W ½ Concession 6, Township of

Eramosa, County of Wellington."

Introduction

Macaulay Shiomi Howson Ltd. retained Unterman McPhail Associates, Heritage Resource Management Consultants, on behalf of the Township of Guelph/Eramosa to participate in the review of a the above-mentioned cultural heritage assessment review report.

This Memorandum has been prepared to provide information with regard to perceived information gaps in the report submitted in June 2013 by Peter Stewart, Architect, of George Robb Architect, Toronto, Ontario, for the Hidden Quarry site in the Township of Eramosa.

Cultural Heritage Report Gaps

The subject report states its intent is the preparation of an assessment of the built heritage resources and cultural heritage landscapes on or adjacent to the proposed Hidden Quarry site and to determine the cultural heritage value or interest of the identified cultural heritage resources. The report contains an historical review of the site and the study area based on local and regional historical sources, aerial photography, historical mapping and current photographs to inform the observations made during a site visit and to support the report assessment.

The subject report includes a site assessment based primarily on existing conditions. The identified heritage resources were not evaluated using criteria for "Determining Cultural Heritage Value" set out in the O. Reg. 09/06 under the Ontario Heritage Act. Based upon our review of the subject report, there appear to be 'information gaps' related to historical research, the lack of detailed mapping for the site and adjacent lands and no municipal consultation. The following 'information gaps' are identified.

 The subject report does not refer to the existing MTCS Checklist (Screening for Impacts to Built Heritage and Cultural Heritage Landscapes, November 2010) as

a tool to provide a basis to scope the requirements of the assessment.

- 2. The subject report does not include a detailed history on the Hopkins, Ramshaw, Johnson or Shaw families and their roles, influence or importance to local settlement and the community as related to property.
- 3. An summary of the history of the earlier quarry operations on site, the role the quarry played in local history, who ran the extraction business, and duration of time the industry operated on site would provide contextual history to assist in the assessment of historical and associative value.
- 4. Section 4.0 notes three (3) properties located along Sixth Line to the 'north of the site', namely, the Day property (4963), the Ferries property (4958) and the Dryden property (5006). There is no mention of the consultant contacting the local municipality to confirm if the three buildings are listed on a municipal register, municipally designated under the OHA or included on a municipal inventory of non-registered heritage property of local interest or merit.
- 5. As well the subject report does not include a map showing the location of the three (3) properties, i.e., the Day property at 4963 Sixth Line, the Ferries property at 4958 Sixth Line and the Dryden property at 5006 Sixth Line in relation to the quarry site. A map would provide better reference for the proximity of the identified properties to the development site. As well it would assist in assessing potential impacts to the heritage character of the three properties resulting from an operating quarry with regard to changes resulting from the introduction of new audible, visual or atmospheric conditions that may affect the properties.
- 6. Section 5.2 of the subject report identifies five (5) properties located within a '120 m off-site zone', and describes all properties as 'unremarkable'. There is no mention of the consultant contacting the local municipality to confirm if the five buildings are listed on a municipal register, municipally designated under the OHA or included on a municipal inventory of non-registered heritage property of local interest or merit. The five properties should be identified as non-heritage resources for clarity purposes rather than 'unremarkable'.
- 7. The five (5) properties mentioned in Section 5.2 should be identified on a map contained in the subject map that shows the relationship of the '120 m off site zone' to the quarry site.
- 8. Appendix B Site Photography of the subject report does not include a photo key plan/map to identify the location of the images within the context of the quarry site location.

It is recommended the 'information gaps' described above be included in the subject report, "Cultural Heritage Assessment Review for the proposed Hidden Quarry, Part Lot 1 W ½ Concession 6, Township of Eramosa, County of Wellington" (June 2013).



UNTERMAN McPHAIL ASSOCIATES

HERITAGE RESOURCE MANAGEMENT CONSULTANTS

540 RUNNYMEDE ROAD TORONTO ONTARIO M6S 2Z7

T 416 766 7333 F 416 763 4082

E umcarubm@pathcom.com

memorandum

to: Liz Howson, Principal

Macaulay Shiomi Howson Ltd., Toronto, ON

from: Richard Unterman, Principal

date: October 1, 2014

re: Review of September 8, 2014 Revised "Cultural Heritage Assessment Review for the

proposed Hidden Quarry, Part Lot 1 W1/2, Concession 6, Township of Eramosa,

County of Wellington."

Introduction

Macaulay Shiomi Howson Ltd. retained Unterman McPhail Associates, Heritage Resource Management Consultants, on behalf of the Township of Eramosa to participate in the review of the study report for the above-mentioned project.

This Memorandum is presented to provide information relating to the "revised" Cultural Heritage Technical report submitted by Peter Stewart, Architect, George Robb Architect, Toronto, Ontario.

Cultural Heritage Report Gaps

The report states the intent of the Cultural Heritage Assessment Review was the preparation of an assessment of the built heritage resources and cultural heritage landscapes on or adjacent to the proposed Hidden Quarry site. The intent of the report was the determination of the cultural heritage value or interest of resources within the study area. The author completed a historical review of the site and study area using local and regional sources including aerial photography, historical mapping and photographs to support the analysis. The historical research informed the observations made during the site visit.

Based upon our review of the original study report we confirmed the existence of 'information gaps' related to the level of historical research, the survey, as well as a need for more detailed mapping of the site and abutting lands. The following gaps were identified in the original cultural heritage assessment report:

- 1. The subject report does not refer to the existing MTCS Checklist (Screening for Impacts to Built Heritage and Cultural Heritage Landscapes, November 2010) as a tool to provide a basis to scope the requirements of the assessment.
- The subject report does not include a detailed history on the Hopkins,
 Ramshaw, Johnson or Shaw families and their roles, influence or importance to local settlement and the community as related to property.
- 3. An summary of the history of the earlier quarry operations on site, the role the quarry played in local history, who ran the extraction business, and duration of time the industry operated on site would provide contextual history to assist in the assessment of historical and associative value.
- 4. Section 4.0 notes three (3) properties located along Sixth Line to the 'north of the site', namely, the Day property (4963), the Ferries property (4958) and the Dryden property (5006). There is no mention of the consultant contacting the local municipality to confirm if the three buildings are listed on a municipal register, municipally designated under the OHA or included on a municipal inventory of non-registered heritage property of local interest or merit.
- 5. As well the subject report does not include a map showing the location of the three (3) properties, i.e., the Day property at 4963 Sixth Line, the Ferries property at 4958 Sixth Line and the Dryden property at 5006 Sixth Line in relation to the quarry site. A map would provide better reference for the proximity of the identified properties to the development site. As well it would assist in assessing potential impacts to the heritage character of the three properties resulting from an operating quarry with regard to changes resulting from the introduction of new audible, visual or atmospheric conditions that may affect the properties.
- 6. Section 5.2 of the subject report identifies five (5) properties located within a '120 m off-site zone', and describes all properties as 'unremarkable'. There is no mention of the consultant contacting the local municipality to confirm if the five buildings are listed on a municipal register, municipally designated under the OHA or included on a municipal inventory of non-registered heritage property of local interest or merit. The five properties should be identified as non-heritage resources for clarity purposes rather than 'unremarkable'.
- 7. The five (5) properties mentioned in Section 5.2 should be identified on a map contained in the subject map that shows the relationship of the '120 m off site zone' to the quarry site.
- 8. Appendix B Site Photography of the subject report does not include a photo key plan/map to identify the location of the images within the context of the quarry site location.

It was recommended the 'information gaps' described above be included in the subject report, "Cultural Heritage Assessment Review for the proposed Hidden Quarry, Part Lot 1 W ½ Concession 6, Township of Eramosa, County of Wellington" (June 2013).

The revised September 8, 2014 study document does address most 'information gaps'. However, there are still some areas of weakness in the report. Point #2 noted that more information on the family histories would be useful. Further family resident research would enhance the review of the historical significance of the property. A more detailed understanding of the family contribution to the community is of interest and can be used in evaluating historical significance.

No further research or information on the quarrying activities was introduced in the revised document as mentioned in Point #3. Was this undertaken?

Lastly, to better understand the conceptual site design and the mitigation measures discussed in the Cultural Heritage Resource Assessment, it is recommended that the proposed site plan drawing be appended to the report. Showing the identified properties in reference to the site plan design would enhance the community understanding of the identified cultural heritage resources in relation to the planned quarry site.

GEORGE ROBB ARCHITECT

January 26, 2015

Mr. Greg Sweetnam
James Dick Construction Limited
The James Dick Group
PO Box 470
Bolton, Ontario
L7E 5T4

4800 DUNDAS STREET WEST SUITE TWO HUNDRED & ONE TORONTO, ONTARIO CANADA M9A 1B1 PHONE: 416 596 8301 FAX: 416 596 1508

Dear Greg,

Re Cultural Heritage Resource Assessment
Hidden Quarry, Part Lot 1 W1/2, Concession 6
Township of Eramosa, County of Wellington

Further to your email of last Thursday and Mr. Unterman's comments of October 1, 2014, I would like to respond as follows.

- a. We were asked to provide "detailed history on the Hopkins, Ramshaw, Johnson or Shaw families..." and their roles in the community. Since this research had already been done by York North Archaeological Services Inc. in their report of August 31, 2012, we incorporated their work (with credit) outlining the history of ownership of the property through the Hopkins, Ramshaw, Johnson and Shaw periods (from the patent in 1822).
- b. No further information on the quarrying activity was found. Its limited size may very well indicate the quarry was only of small scale local work. The analysis of air photos indicates some local disturbances of quarry activity from 1954 to 1985. By 1994, quarry is no longer indicated on the topographical maps.
- c. We have used the applicant's Existing Features Site Plan to locate photographic points of view. Certainly the applicant's submission has an abundance of Site Plans depicting different aspects of the development. Can Mr. Unterman identify which Site Plan may best enhance community understanding?

We trust this is as you require.

Peter Stewart b.arch OAA CAHP



UNTERMAN McPHAIL ASSOCIATES

HERITAGE RESOURCE MANAGEMENT CONSULTANTS

540 RUNNYMEDE ROAD TORONTO ONTARIO M6S 2Z7

T 416 766 7333 F 416 763 4082

E umcarubm@pathcom.com

memorandum

to: Liz Howson, Principal

Macaulay Shiomi Howson Ltd., Toronto, ON

from: Richard Unterman, Principal

date: August 26, 2015

re: Review of September 8, 2014 Revised "Cultural Heritage Assessment Review for the

proposed Hidden Quarry, Part Lot 1 W1/2, Concession 6, Township of Eramosa,

County of Wellington."

Introduction

Macaulay Shiomi Howson Ltd. retained Unterman McPhail Associates, Heritage Resource Management Consultants, on behalf of the Township of Eramosa to participate in the review of the study report for the above-mentioned project.

This Memorandum is presented to provide information relating to the "revised" Cultural Heritage Technical report submitted by Peter Stewart, Architect, George Robb Architect, Toronto, Ontario.

Cultural Heritage Report Gaps

The report states the intent of the Cultural Heritage Assessment Review was the preparation of an assessment of the built heritage resources and cultural heritage landscapes on or adjacent to the proposed Hidden Quarry site. The intent of the report was the determination of the cultural heritage value or interest of resources within the study area. The author completed a historical review of the site and study area using local and regional sources including aerial photography, historical mapping and photographs to support the analysis. The historical research informed the observations made during the site visit.

Based upon our review of the original study report we confirmed the existence of 'information gaps' related to the level of historical research, the survey, as well as a need for more detailed mapping of the site and abutting lands. The following gaps were identified in the original cultural heritage assessment report:

- The subject report does not refer to the existing MTCS Checklist (Screening for Impacts to Built Heritage and Cultural Heritage Landscapes, November 2010) as a tool to provide a basis to scope the requirements of the assessment.
- The subject report does not include a detailed history on the Hopkins,
 Ramshaw, Johnson or Shaw families and their roles, influence or importance to local settlement and the community as related to property.
- 3. An summary of the history of the earlier quarry operations on site, the role the quarry played in local history, who ran the extraction business, and duration of time the industry operated on site would provide contextual history to assist in the assessment of historical and associative value.
- 4. Section 4.0 notes three (3) properties located along Sixth Line to the 'north of the site', namely, the Day property (4963), the Ferries property (4958) and the Dryden property (5006). There is no mention of the consultant contacting the local municipality to confirm if the three buildings are listed on a municipal register, municipally designated under the OHA or included on a municipal inventory of non-registered heritage property of local interest or merit.
- 5. As well the subject report does not include a map showing the location of the three (3) properties, i.e., the Day property at 4963 Sixth Line, the Ferries property at 4958 Sixth Line and the Dryden property at 5006 Sixth Line in relation to the quarry site. A map would provide better reference for the proximity of the identified properties to the development site. As well it would assist in assessing potential impacts to the heritage character of the three properties resulting from an operating quarry with regard to changes resulting from the introduction of new audible, visual or atmospheric conditions that may affect the properties.
- 6. Section 5.2 of the subject report identifies five (5) properties located within a '120 m off-site zone', and describes all properties as 'unremarkable'. There is no mention of the consultant contacting the local municipality to confirm if the five buildings are listed on a municipal register, municipally designated under the OHA or included on a municipal inventory of non-registered heritage property of local interest or merit. The five properties should be identified as non-heritage resources for clarity purposes rather than 'unremarkable'.
- 7. The five (5) properties mentioned in Section 5.2 should be identified on a map contained in the subject map that shows the relationship of the '120 m off site zone' to the quarry site.
- 8. Appendix B Site Photography of the subject report does not include a photo key plan/map to identify the location of the images within the context of the quarry site location.

It was recommended the 'information gaps' described above be included in the subject report, "Cultural Heritage Assessment Review for the proposed Hidden Quarry, Part Lot 1 W ½ Concession 6, Township of Eramosa, County of Wellington" (June 2013).

The revised September 8, 2014 study document does address most 'information gaps'. However, there are still some areas of weakness in the report. It would be of benefit to the overall study if more information on the family histories were provided. This is not a major issue and can be completed in the future, if deemed necessary to enhance any commemorative history relating to the study area.

No further research or information on the quarrying activities was introduced in the revised document as mentioned in Point #3. We presume this information was not found through more detailed research, as the quarrying activity may have been of a temporary nature and not documented.

To better understand the conceptual site design and the mitigation measures discussed in the Cultural Heritage Resource Assessment, it is recommended that the when the final site plan drawing is available, it be appended to the report. Showing the identified properties in reference to the conceptual site plan design would enhance the community understanding of the cultural heritage resources in relation to the planned quarry site.